

Приложение к Чертежу красных линий
Перечень координат характерных точек устанавливаемых красных линий

Номер точки	Координаты	
	X	Y
Контур 1		
1	368743.75	2191242.68
2	368716.93	2191272.34
3	368690.11	2191302.02
Контур 2		
1	368512.02	2191092.25
2	368512.29	2191146.08
3	368514.66	2191147.82
4	368526.18	2191157.94
5	368544.96	2191174.45
6	368563.74	2191190.95
7	368582.52	2191207.45
8	368601.29	2191223.96
9	368620.07	2191240.46
10	368638.85	2191256.97
11	368657.63	2191273.47
12	368676.41	2191289.97
13	368703.67	2191260.68
14	368730.94	2191231.39
15	368710.44	2191213.38
16	368691.65	2191196.88
17	368672.88	2191180.37
18	368654.11	2191163.87
19	368635.33	2191147.36
20	368616.55	2191130.86
21	368597.77	2191114.36

Номер точки	Координаты	
	X	Y
22	368578.99	2191097.85
23	368558.33	2191079.70
24	368529.41	2191054.28
1	368512.02	2191092.25
Контур 3		
1	368515.33	2191249.91
2	368514.57	2191211.64
3	368513.92	2191178.66
4	368513.42	2191162.71
5	368553.63	2191198.04
6	368580.42	2191221.59
7	368599.20	2191238.09
8	368617.86	2191254.49
9	368637.71	2191271.94
10	368668.23	2191298.76
11	368682.05	2191310.94
Контур 4		
1	368528.29	2191028.87
2	368519.88	2191049.98
3	368494.36	2191106.57
4	368498.42	2191163.06
5	368500.46	2191250.26
Контур 5		
1	368559.96	2191033.30
2	368753.27	2191232.08
3	368753.06	2191231.89